

ValleyRide Rail Corridor Study Bridge Inventory and Proposed Improvements

Bridge No.	Location	Description	General Condition	Proposed Improvements
443.10	Gowen Road	Roadway Overcrossing	Good condition	
443.34	I-84	Interstate Highway Overcrossing	Good condition	
446.07	New York Canal	Thru Girder Open Deck	Bridge ties damaged by derailment and plate cut.	Replace 80 bridge ties
446.08	Broadway Avenue	Roadway Overcrossing	Good condition	
446.30	Wright Street	Arch Plate Culvert, Pvt Road Undercrossing	Good condition	
448.22	Ridenbaugh Canal	Deck Plate Girder Open Deck	Some bridge ties damaged, timber handrail in fair condition.	Replace 10 bridge ties, replace handrail
448.50	Vista Avenue	Thru Girder Ballast Deck	Good condition	
448.93	Ridenbaugh Canal	Timber Trestle Open Deck	Good condition	
450.93	Ridenbaugh Canal	Deck Beam Ballast Deck	Good condition	
451.81	I-84	Interstate Highway Overcrossing	Good condition	
452.75	Ridenbaugh Canal	Deck Beam Ballast Deck	Good condition	
464.00	Phillie Canal	Deck Beam Ballast Deck	Good condition	
465.64	Phillie Canal	Deck Girder Open Deck	Good condition	
465.76	I-84	Interstate Highway Overcrossing	Good condition	
466.54	Garrity Boulevard	Deck Girder Ballast Deck	Good condition	
467.35	Third Street	Deck Girder Ballast Deck	Good condition	
467.46	Indian Creek	Deck Girder Ballast Deck	Good condition	
467.54	1st Street Extension	Timber Frame Trestle Open Deck	Concrete abutments cracking, stringers and posts damaged by road traffic.	Replace entire structure.